

Summary of Facility Information in the County of Dawson

Owner Name and Address: Farmers Union Oil Co Bloomfield PO Box 15 Bloomfield MT 59315 Phone: (406) 583-7539

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1104222	Farmers Union Oil Co Bloomfield	Road 254	Bloomfield	59315	(406) 583-7539

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
3 / 03 Currently in Use	950	11/28/1988 17 / No	Gasoline 4,000	STI-P3 None	Bare Steel Cathodically Protected	Safe Suction	<div> <div>A B C D <input checked="" type="radio"/> F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	<div> <div>A B C D <input checked="" type="radio"/> F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Dawson

Owner Name and Address: Gregory Cross PO Box 1388 Glendive MT 59330 Phone: (406) 252-5519

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1100033	East End Conoco Glendive	Interstate 94 & Merrill Ave	Glendive	59330	(406) 365-8325

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
4 / 04 Currently in Use	773	1/17/1989 17 / No	Gasoline 4,000	STI-P3 Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
5 / 05 Currently in Use	774	1/17/1989 17 / No	Gasoline 4,000	STI-P3 Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently in Use	775	1/17/1989 17 / No	Gasoline 4,000	STI-P3 Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Dawson

Owner Name and Address: Dawson County Airport 207 W Bell St Glendive MT 59330 Phone: (406) 377-3025

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1102455	Glendive Airport Large Hanger	402 Dry Creek Road	Glendive	59330	(406) 687-3372

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
4 / 04 Currently in Use	824	11/21/1994 11 / No	Other 8,000	STI-P3 None	Other Double-Walled/Non-Corro	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td><input checked="" type="radio"/></td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	<input checked="" type="radio"/>	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		Yes Yes Yes Yes
A	B	C	D	<input checked="" type="radio"/>	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																						
5 / S5 Currently in Use	825	1/1/1974 32 / Ye	Other 200	Unknown None	Bare Steel Cathodically Protected	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><input checked="" type="radio"/></td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	D	E	F	G	H	I	J	<input checked="" type="radio"/>	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	F	G	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<input checked="" type="radio"/>	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	F	G	H	I	J	K	L																							

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Dawson

Owner Name and Address: Berg Tire 2111 W Towne Glendive MT 59330 Phone: (406) 377-5286

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1103214	Bergs Tire Inc	2111 W Towne St	Glendive	59330	(406) 377-5286

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 09 Currently in Use	601	3/26/1987 19 / No	Gasoline 6,000	STI-P3 Impressed Current	Bare Steel Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 08 Currently in Use	600	3/26/1987 19 / No	Diesel 6,000	STI-P3 Impressed Current	Bare Steel Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 07 Currently in Use	599	3/26/1987 19 / No	Gasoline 12,000	STI-P3 Impressed Current	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
5 / 06 Currently in Use	598	3/26/1987 19 / No	Diesel 12,000	STI-P3 Impressed Current	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Dawson

Owner Name and Address: T & E Whistle Stop Inc 1320 N Merrill Ave PO Box 1313 Glendive MT 59330 Phone: (406) 365-2177

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1104213	T & E Whistle Stop Inc	1320 N Merrill Ave	Glendive	59330	(406) 365-2177

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	4308	5/6/1984 22 / No	Diesel 10,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C D <input checked="" type="radio"/> F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	4309	5/6/1984 22 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C D <input checked="" type="radio"/> F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	4310	5/6/1984 22 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C D <input checked="" type="radio"/> F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Dawson

Owner Name and Address: Mini Mart Inc 442 Keeler Pkwy Pueblo CO 81001 Phone: (719) 948-3071

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1105093	Mini Mart 710 1105093	322 E Barry St	Glendive	59330	(406) 365-6111

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
4 / 04 Currently in Use	1636	9/1/1996 09 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
5 / 05 Currently in Use	1637	9/1/1996 09 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently in Use	1638	9/1/1996 09 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Dawson

Owner Name and Address: Trail Star LLC PO Box 557 Glendive MT 59330 Phone: (406) 377-3901

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1105754	Trail Star Car and Truck Stop	Exit 213 MT Highway 16	Glendive	59330	(406) 365-0557

TankID/Alt TankID	Tag Numb	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
5 / 05 Currently In Use	4274	11/30/1998 07 / No	Gasoline 4,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	D	E	F	●	H	I	J	K	L	B	D	E	F	●	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	D	E	F	●	H	I	J	K	L																					
B	D	E	F	●	H	I	J	K	L																							
6 / 06 Currently In Use	4275	11/30/1998 07 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	D	E	F	●	H	I	J	K	L	B	D	E	F	●	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	D	E	F	●	H	I	J	K	L																					
B	D	E	F	●	H	I	J	K	L																							
7 / 07 Currently In Use	4276	11/30/1998 07 / No	Diesel 12,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	D	E	F	●	H	I	J	K	L	B	D	E	F	●	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	D	E	F	●	H	I	J	K	L																					
B	D	E	F	●	H	I	J	K	L																							
8 / 08 Currently In Use	4277	11/30/1998 07 / No	Diesel 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	D	E	F	●	H	I	J	K	L	B	D	E	F	●	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	D	E	F	●	H	I	J	K	L																					
B	D	E	F	●	H	I	J	K	L																							
9 / 09 Currently In Use	4278	11/30/1998 07 / No	Diesel 15,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	D	E	F	●	H	I	J	K	L	B	D	E	F	●	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	D	E	F	●	H	I	J	K	L																					
B	D	E	F	●	H	I	J	K	L																							

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Dawson

Owner Name and Address: School District 1 PO Box 701 Glendive MT 59330 Phone: (406) 365-4055

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1106648	Jefferson School Bus Barn	800 Jefferson School Road	Glendive	59330	

TankID/Alt TankID	Tag	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met
Status	Numbe	Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C
3 / 03 Currently in Use	1888	7/15/1990 15 / No	Diesel 1,000	Cathodically Protected Steel None	Galvanized Steel Cathodically Protected	Safe Suction	<div style="display: flex; justify-content: space-between; font-size: 0.8em;"> (A) (B) (C) (D) (E) (F) (G) (H) (I) (J) (K) (L) </div> <div style="display: flex; justify-content: space-between; font-size: 0.8em;"> (B) (D) (E) (F) (G) (H) (I) (J) (K) (L) </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Dawson

Owner Name and Address: Qwest Communications 1600 7th Ave Room 2206 Seattle WA 98191 Phone: (206) 346-7532

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1106870	Qwest Glendive Central Office	119 W Valentine St	Glendive	59330	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	1726	4/1/1993 13 / No	Diesel 553	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	<div style="display: flex; justify-content: space-between; font-size: 0.8em;"> (A) (B) (C) (D) (E) (F) (G) (H) (I) (J) (K) (L) </div> <div style="display: flex; justify-content: space-between; font-size: 0.8em;"> (B) (D) (E) (F) (G) (H) (I) (J) (K) (L) </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Dawson

Owner Name and Address: Joys Glendive Service Inc 74 Highway 16 Glendive MT 59330 Phone: (406) 377-1821

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1107770	Joys Glendive Service Inc	74 Highway 16	Glendive	59330	(406) 377-1821

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
6 / 06 Currently In Use	1511	5/28/1998 08 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					
7 / 07 Currently In Use	1512	5/28/1998 08 / No	Gasoline 4,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					
8 / 08 Currently In Use	1513	5/28/1998 08 / No	Diesel 6,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					
9 / 09 Currently In Use	1514	5/28/1998 08 / No	Diesel 2,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Dawson

Owner Name and Address: Rocky Mountain Oil Co Inc 4567 W 80th St PO Box 1224 Minneapolis MN 55440 Phone: (952) 830-8891

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1108061	Holiday Stationstore 271	701 N Merrill Ave	Glendive	59330	(406) 365-2221

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 02 Currently in Use	3002	10/1/1979 26 / No	Gasoline 12,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H <input checked="" type="radio"/> J K L</div> <div>B <input checked="" type="radio"/> E F G H <input checked="" type="radio"/> J K L</div> </div>	Yes Yes Yes Yes
2 / 03 Currently in Use	3003	10/1/1979 26 / No	Gasoline 8,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H <input checked="" type="radio"/> J K L</div> <div>B <input checked="" type="radio"/> E F G H <input checked="" type="radio"/> J K L</div> </div>	Yes Yes Yes Yes
3 / 04 Currently in Use	3004	10/1/1979 26 / No	Diesel 8,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H <input checked="" type="radio"/> J K L</div> <div>B <input checked="" type="radio"/> E F G H <input checked="" type="radio"/> J K L</div> </div>	Yes Yes Yes Yes
4 / 01 Currently in Use	3001	10/1/1979 26 / No	Gasoline 12,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H <input checked="" type="radio"/> J K L</div> <div>B <input checked="" type="radio"/> E F G H <input checked="" type="radio"/> J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Dawson

Owner Name and Address: Cenex Petroleum Inc PO Box 64089 MS 535 Saint Paul MN 55164 Phone: (651) 355-5583

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1108908	Kum and Go Store 809	2200 W Towne St	Glendive	59330	(406) 365-6282

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
4 / S4 Currently in Use	553	9/1/1999 06 / Ye	Gasoline 12,000	Unknown None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div>	Yes Yes Yes Yes
5 / S5 Currently in Use	554	9/1/1999 06 / Ye	Gasoline 12,000	Unknown None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div>	Yes Yes Yes Yes
6 / S6 Currently in Use	555	9/1/1999 06 / Ye	Diesel 10,000	Unknown None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Dawson

Owner Name and Address: Gregory Cross PO Box 1388 Glendive MT 59330 Phone: (406) 252-5519

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1108909	Westgate Glendive	56 MT Highway 16	Glendive	59330	(406) 365-8325

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently In Use	556	5/22/1961 45 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently In Use	557	5/22/1961 45 / No	Diesel 8,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
5 / 05 Currently In Use	558	2/7/1992 14 / No	Gasoline 10,000	STI-P3 Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Dawson

Owner Name and Address: Montana Dakota Utilities Company 400 N 4th St Bismarck ND 58501 Phone: (800) 472-2150

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1109400	Glendive Combustion Turbine	366 FAS 355	Glendive	59330	(406) 365-2551

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
1 / S2 Currently in Use	1692	7/1/1987 19 / Ye	Diesel 75,000	Cathodically Protected Steel None	Bare Steel Double-Walled/Non-Corro	U.S. Suction	<div> <div>A B C D E F G H I J <input checked="" type="radio"/> L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	<div> <div>A B C D E F G H I J <input checked="" type="radio"/> L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Dawson

Owner Name and Address: Glendive Medical Center 202 Prospect Dr Glendive MT 59330 Phone: (406) 345-3306

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1109735	Glendive Medical Center	202 Prospect Dr	Glendive	59330	(406) 345-3306

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
Status									Spill/Overl/C
1 / 03 Currently in Use	1223	11/16/1995 10 / No	Diesel 4,010	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Dawson

Owner Name and Address: Elmer Heinrich 1717 N Merrill Ave Glendive MT 59330 Phone: (406) 377-3650

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1109770	Interstate Sinclair Glendive	1717 N Merrill Ave	Glendive	59330	(406) 365-3650

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																											
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																											
3 / 03 Currently in Use	1291	7/1/1991 15 / No	Diesel 6,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td></td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L		B					<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																								
	B					<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
4 / 04 Currently In Use	1292	2/21/1998 08 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td><input checked="" type="radio"/></td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		<input checked="" type="radio"/>			<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes		
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																								
	<input checked="" type="radio"/>			<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																							
5 / 05 Currently In Use	1293	2/21/1998 08 / No	Gasoline 5,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td><input checked="" type="radio"/></td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		<input checked="" type="radio"/>			<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes		
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																								
	<input checked="" type="radio"/>			<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																							
6 / 06 Currently In Use	1294	2/21/1998 08 / No	Diesel 3,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td><input checked="" type="radio"/></td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		<input checked="" type="radio"/>			<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes		
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																								
	<input checked="" type="radio"/>			<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																							

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Dawson

Owner Name and Address: Gregory Cross PO Box 1388 Glendive MT 59330 Phone: (406) 252-5519

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613872	Crossroads Conoco Glendive	58 MT Highway 16	Glendive	59330	(406) 365-2728

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently In Use	4043	6/26/1999 07 / No	Diesel 10,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently In Use	4044	6/26/1999 07 / No	Gasoline 15,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently In Use	4045	6/26/1999 07 / No	Gasoline 10,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Dawson

Owner Name and Address: Cenex Harvest States Coop Richey PO Box 64089 Saint Paul MN 55164 Phone: (800) 232-3639

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1105898	Farmers Elevator Co Richey	111 Railroad Ave	Richey	59259	(406) 773-5638

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
5 / 05 Currently In Use	4314	7/11/2001 04 / No	Diesel 4,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently In Use	4315	7/11/2001 04 / No	Gasoline 4,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
7 / 07 Currently In Use	4316	7/11/2001 04 / No	Diesel 4,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed